






# HO 40' Steel Ice Reefer

Announced 08.26.16  
Available for Backorder



ETA: July 2017

## BN / Western Fruit Express





- RND86060 HO 40' Steel Reefer, BN/WFE #704614
- RND86061 HO 40' Steel Reefer, BN/WFE #704662
- RND86062 HO 40' Steel Reefer, BN/WFE #704738

## Chicago, Burlington & Quincy





- RND86063 HO 40' Steel Reefer, CB&Q #74255
- RND86064 HO 40' Steel Reefer, CB&Q #74280
- RND86065 HO 40' Steel Reefer, CB&Q #74398

## Fruit Growers Express



- RND86066 HO 40' Steel Reefer, FGE #38520
- RND86067 HO 40' Steel Reefer, FGE #38947
- RND86068 HO 40' Steel Reefer, FGE #38999

## Great Northern



- RND86069 HO 40' Steel Reefer, GN #70116
- RND87882 HO 40' Steel Reefer, GN #70598
- RND87883 HO 40' Steel Reefer, GN #70807

\$24.98<sup>SRP</sup>






Visit Your Local Retailer | Visit [www.athearn.com](http://www.athearn.com) | Call 1.800.338.4639



# HO 40' Steel Ice Reefer Merchants Dispatch




Announced 08.26.16  
Available for Backorder

ETA: July 2017





RND87884 HO 40' Steel Reefer, MDT #11945  
RND87885 HO 40' Steel Reefer, MDT #11957  
RND87886 HO 40' Steel Reefer, MDT #12523

## Pacific Fruit Express (green)\*






RND87887 HO 40' Steel Reefer, PFE/Green #911  
RND87888 HO 40' Steel Reefer, PFE/Green #927  
RND87889 HO 40' Steel Reefer, PFE/Green #945

## Pacific Fruit Express (Overland)\*



RND87890 HO 40' Steel Reefer, PFE/Overland #40452  
RND87891 HO 40' Steel Reefer, PFE/Overland #42257  
RND87892 HO 40' Steel Reefer, PFE/Overland #43801

## Rock Island



RND87893 HO 40' Steel Reefer, RI #67002  
RND87894 HO 40' Steel Reefer, RI #67027  
RND87895 HO 40' Steel Reefer, RI #67088

**\$24.98**SRP



Visit Your Local Retailer | Visit [www.athearn.com](http://www.athearn.com) | Call 1.800.338.4639

\* Union Pacific Licensed Product





# HO 40' Steel Ice Reefer

Announced 08.26.16  
Available for Backorder

## SOO Line

ETA: July 2017



RND87896	HO 40' Steel Reefer, SOO #11000
RND87897	HO 40' Steel Reefer, SOO #11032
RND87898	HO 40' Steel Reefer, SOO #11046

## All Road Names

### MODEL FEATURES:

- Fully-assembled and ready to run out of the box
- Highly-detailed, injection-molded body
- McHenry scale knuckle spring couplers installed
- Painted and printed for realistic decoration
- Weighted for trouble free operation
- 33" machined metal wheels with RP25 contours operate on all popular brands of track
- Body mounted McHenry operating scale knuckle couplers
- Window packaging for easy viewing plus interior plastic blister safely holds the model for convenient storage
- Replacement parts available
- Minimum radius: 18"

### PROTOTYPE AND BACKGROUND INFO:

The use of ice to refrigerate and preserve food dates back to prehistoric times. Through the ages, the seasonal harvesting of snow and ice was a regular practice of many cultures. By the turn of the 20th century, manufactured ice became more common. The Pacific Fruit Express (PFE), for example, maintained seven natural harvesting facilities, and operated 18 artificial ice plants. Their largest plant (located in Roseville, California) produced 1,100 tons of ice daily, and Roseville's docks could accommodate up to 254 cars. At the industry's peak, 1,200,000 tons of ice was produced for refrigerator car use annually.

A late-19th century wood-bodied reefer required re-icing every 250 miles (400 km) to 400 miles (640 km). The typical ice-bunker reefer from the 1920s were originally constructed with wood sheathing. Later, these early wood constructed cars would be replaced with steel constructed cars with plywood interiors by the 1940s. Vents in the bunker at the end of the car, along with slots in the wood floor racks, allowed cool air to circulate around the contents.

**\$24.98**SRP



Visit Your Local Retailer | Visit [www.athearn.com](http://www.athearn.com) | Call 1.800.338.4639