





Announced: 1-28-12
Orders Due: 2-17-12
 ETA: November 2012

EMD GP38-2



___ G40512	No Sound	\$179.98*	___ G40612	Sound	\$279.98*	GP38-2 Southern Pacific #4800
___ G40513	No Sound	\$179.98*	___ G40613	Sound	\$279.98*	GP38-2 Southern Pacific #4812
___ G40514	No Sound	\$179.98*	___ G40614	Sound	\$279.98*	GP38-2 Southern Pacific #4822
___ G40515	No Sound	\$179.98*	___ G40615	Sound	\$279.98*	GP38-2 Southern Pacific #4837



___ G40504	No Sound	\$179.98*	___ G40604	Sound	\$279.98*	GP38-2 Missouri Pacific #2114
___ G40505	No Sound	\$179.98*	___ G40605	Sound	\$279.98*	GP38-2 Missouri Pacific #2117
___ G40506	No Sound	\$179.98*	___ G40606	Sound	\$279.98*	GP38-2 Missouri Pacific #2121
___ G40507	No Sound	\$179.98*	___ G40607	Sound	\$279.98*	GP38-2 Missouri Pacific #2126

GP38-2 Era: 1972 to present

- All-new tooling
- "Notched" stepwells on SP units
- Standard stepwells on MP units
- Round "shotgun" stacks on SP units
- Extra modeler-applied stacks and arrestors for MP
- Non-sound units are DCC ready using Quick Plug™ technology
- Sound units have Soundtraxx Tsunami™ factory installed
- McHenry® scale knuckle spring couplers
- Prototype specific details per phase and prototype, such as:
 - Radiator grilles
 - Dynamic brakes
 - Sunshades
 - PAF Box or oil-bath filters
 - Bells
 - Many headlight options
- Separately applied wire grab irons
- Etched radiator fan grills
- Window glazing
- Operating headlights utilizing microbulbs
- Extra jacking pads on MP units
- Fuel tanks
- Battery access doors
- Cut Levers
- Lost-wax brass air horns
- Truck sideframes
- Antennas
- Fan spacing
- ECAFBs
- MU stands
- Walkway duct lengths
- Pilot details
- Stepwells

Athearn Trains • 1600 Forbes Way • Suite 120 • Long Beach, CA • 90810
 310-763-7140 • 877-422-9316 • fax 310-895-7484 • www.athearn.com