




Announced: 9-21-10
Orders Due: 10-15-10
 ETA: March 2011

50' PC&F Box Car 8' + 6' Landis Doors



- ___ G69018 Southern Pacific #693376 \$37.98*
- ___ G69019 Southern Pacific #693535 \$37.98*
- ___ G69020 Southern Pacific #693880 \$37.98*
- ___ G69021 Southern Pacific #694187 \$37.98*



- ___ G69022 Southern Pacific #693764 \$37.98*
- ___ G69023 Southern Pacific #694001 \$37.98*
- ___ G69024 Southern Pacific #694073 \$37.98*
- ___ G69025 Southern Pacific #694209 \$37.98*

These four cars will have consolidated lube plates



- ___ G69026 SSW/Cotton Belt #25682 \$37.98*
- ___ G69027 SSW/Cotton Belt #25735 \$37.98*
- ___ G69028 SSW/Cotton Belt #25853 \$37.98*
- ___ G69029 SSW/Cotton Belt #25966 \$37.98*



- ___ G69030 SSW/Cotton Belt #25619 \$37.98*
- ___ G69031 SSW/Cotton Belt #25707 \$37.98*
- ___ G69032 SSW/Cotton Belt #25864 \$37.98*
- ___ G69033 SSW/Cotton Belt #25913 \$37.98*
- ___ G69017 Undecorated \$37.98

These four cars will have consolidated lube plates

ERA: Late 1960s to 1990s

- Genesis-level detail including:
- Photo-etched cross-over end walks
- Separately applied door rods and operating hardware
- Wire form grab irons
- Train line, brake hoses and hardware
- Coupler lift bars
- .110" tread machined metal wheel sets and operating bearing caps
- McHenry® scale knuckle spring couplers
- Laser-sharp printing
- Weighted for optimal performance

Athearn Trains • 2883 East Spring Street • Suite 100 • Long Beach, CA • 90806
 310-763-7140 • fax 562-427-0536 • www.athearn.com